

## FDR Finishing Checklist

After compaction nears completion on a FDR project, there are a few finishing steps that should be taken. Below is a checklist of those steps.

Note that some specifications described in the following content may not be the same as the specifications followed by your agency. Always check with your State agency's standards and specifications when using these guidelines.

### Sections

- **Finishing Steps**

### Finishing Steps

- Shape the surface of the FDR to the specified lines, grades, and cross sections**
- Continue final compaction**
  - During the last stage of compaction and the first stage of initial curing, the surface of the reclaimed mixture may be dampened with a light application of water and the surface sealed by rolling with a pneumatic-tired roller
  - This prevents the surface from drying out helping to prevent surface cracking and raveling
- Keep the surface moist using a fine spray of water that does not erode the surface**
- Goal is to produce a surface free of compaction planes, cracks, ridges, or loose material**